

■ **CLASS DISCUSSION ITEM 10.2**

Eddy Currents

Describe the causes of eddy currents that are induced in a conducting material experiencing a changing magnetic field. The iron core in a motor rotor is usually laminated. Explain why. What is the best orientation for the laminations?